



CARM I O L I N D U S T R I A L S . A .
200 North of F A C O
San José, Costa Rica
Tel. (506) 2240-3836
carmiolindustrial@ice.co.cr www.carmiolindustrial.com

C I 3 0 5

LARGE CLEANOUT

To have access to large pipe lines , tanks or any other place where a larger access area is necessary .

SCALE NONE

DATE OF LAST CHANGE: 05-12-16


DATE: 04-27-09

APPROVED BY: AC

REVIEWED BY: AC

DRAWN BY: TV

All dimensions are subject to manufacturing tolerances and may change without notice



Ø D inches (mm)	M A T E R I A L	F I N I S H	A inches (mm)	Ø B inches (mm)	Ø C inches (mm)	Ø E inches (mm)
8 " (200)	A = a l u m i n u m B = b r o n z e	A d = n o n - s l i p S = s a t i n	9 - 3 / 4 " (248)	8 " (200)	7 / 8 " (22)	9 " (230)
9 " (230)			11 - 1 / 4 " (286)	9 " (230)	7 / 8 " (22)	10 - 3 / 16 " (259)
9 - 1 / 2 " (240)			12 " (305)	9 - 1 / 2 " (241)	7 / 8 " (22)	10 - 1 / 2 " (268)
10 " (250)			13 - 13 / 16 " (350)	10 - 1 / 4 " (260)	15 / 16 " (24)	12 " (305)

DRAWING NUMBER:
0752009